vMax Commander 5.18, released on February 11th, 2018, introduces important new features and many other relevant improvements.

NEW FEATURES

DS2 Support

- vMax Commander now supports downloading of video files and events from the two-camera vehicle event recording system DS2.


- DS2 video files can be downloaded and deleted at any time.

- While for other video recorders vMax Commander launches vMax View, DS2 video files play back on the system's own DS2 Mini Player.

NX16 Support

vMax Commander supports deleting of archived NX16 recorders video files.

IMPROVEMENTS

Alarms

- For TH4 recorders, vMax Commander adds a new 5th Alarm to the **Alarm** menu, reserved for integration with driver behaviour applications.

- The **Alarms** tab provides more flexibility with a newly-labeled **FTP Upload** column which replaces the previous, more specific **Stop Arm** Alarm label.

Bug Fixes

- This release resolves an error where users could not set their vehicle as "**Out of Service**" if their username had more than 10 characters.

- The message "**Data Not Downloaded Yet**" replaces a previous message reading "No Records Found" when telemetry tasks had not been created.

- Once **NX16 Schedule DVR Configuration Update** is completed, the system now shows "In Progress" as current Status.

Some features request specific permission settings. Please contact Seon if you need more information.

Email: service@seon.com
Phone: **1.844.899.7366**