## **Changing IP address for IP Camera**

- 1. Changing all the exe.config files in C:\Program Files (x86)\COBAN Technologies, Inc\COBAN CommandSystem
- Change the IP address for the Web.config file
  C:\inetpub\wwwroot\Coban\ and C:\inetpub\wwwroot\Coban\CobanPlayer
- 3. Changed the IP camera IP address

• Basic Setup	Basic TCP/IP Settings	0							
Instructions	Network Settings								
1 Users 2 TCP/IP	View current network settings: View								
3 Date & Time 4 Video Stream 5 Focus & Zoom	IPv4 Address Configuration								
	✓ Enable IPv4								
6 Audio Settings	Obtain IP address via DHCP								
Video & Audio	Output Use the following IP address:								
	IP address: 10.122.10.8 Test								
Live View Config	Subnet mask: 255.255.254.0								
Detectors	Default router: 10.122.10.1								
Applications	IPv6 Address Configuration								
	Enable IPv6								
Events	Services								
Recordings	Enable ARP/Ping setting of IP Address								
System Options	Enable AVHS								
	One-click enabled								
About	Proxy:								
	Proxy port: 3128								
	Proxy login:								
	Proxy password:								
	Provy authentication methods () name () piccot () Auto								
	Ploxy addientication method. S Basic Digest O Auto								
	AXIS Internet Dynamic DNS Service Settings								

- 4. Restart the Services
- 5. Login to CCC. If you unable to launch the CCC, make sure the IIS binding is to the correct IP address

Internet Information Services (IIS)	Manager	
File View Help		
Conservation Application Pools → Clos24 (AURORALcmartin) → Application Pools → Closent → Clos	COBAN Home	Actions Explore Edit Stie Edit Stie Edit Stie Bail: Eatting View Applications View Applications Notes Particle Request Tractog () Halp Online Help
Ready		<b>1</b> .

- 6. Add the new IP address to the trusted site. (Note, make sure all the Client machines also added to the trusted site
- 7. Make sure the Storage> Primary Disk > Storage Name have the correct IP address. If it is the servername, it will be fine.
- 8. Change IP address for the Camera itself. To get the Save button, click here

(a) (a) http://10.120.10.1	<b>10</b> :801/			-	_	,0 - C X	🖉 Live view	- AXIS P3364 Networ 🛔	5 10.120.10.10	×									
COBAN									888868	ASSOCIATION OF									6/9/2015
COMMAND CENT	.2.464	Save Discard	Add Sen	O-O-	Add Car	mera			202225										1:26 PM
Users	~	Category	^	ID	Protocol	10 Address	0.000	Stream Name	App Server Type	Camera Name	Camera Type	Streaming Profil	e Recording Profile	Active	Switchbox	Default Event	Default User	Last Update	Last Update By
Groups	v	i General		-	RTSP .	root:coban	\$10.120.10.11	axis-media/media.am	p	IA1	On-demand	Medium -	Medium			Interview Room -	Officer, 1111	5/13/2015 10:37:17 AM	Coban Admin
Roles	~	I Network																	
Templates	¥	I Advanced																	
Patrol Units	~	( Camera																	
Events	~	I Scope																	
Servers	^																		

9. Change CobanIPStage IP address

Users	~	Category	Advanced: Internal Affairs Inte	Advanced: Internal Affairs Interview Room									
Groups	*	i General	Low SD Card Threshold (%)	60	0								
Roles	*	I Network	High SD Card Threshold (%)	80	0								
Templates	~	( Advanced	Run Away Time (Hrs)	8	0								
Patrol Units	~	Camera	Coban IP Stage	\\10.120.10.10\cobanIPstage	0								
events	-		Coban Physical IP Stage Location	c:\cobanIPstage	0								
Servers	^		IP Camera Sync Time	23:45	0								
> III Main			Runaway Recording Timer	1800	0								
Internal Affairs Inter	view Room		SD Disk Space Timer	1800	0								
			Recording Sync Time	5	0								
			Wait time before moving camera i	recordings 60	0								
			Recording Split Mode	7	0								
			Last Update	6/9/2015 1:23:26 PM	0								
			Last Update By	Coban Admin	0								

- 10. Restart Coban System and make sure the other Coban Agent services are running.
- 11. Retest the Interviewroom system