

vMax Trac Install Guide

Install Kit Contents

- Card Reader 065-1000
- GPS4-CBL
- Hex Self Drive Screws (4) 600-0038
- Install Guide 700-1010

LED Functions

- Red, lit Ready for reading
- Green, lit Reading

Installation Steps

1. Unscrew the retainer screw at the bottom of the card reader and remove the back plate.



2. Position the back plate of the card reader on the vehicle surface and mark screw and center hole positions.



3. Drill out the ½" center hole and mount the backing plate with the 4 self tapping hex head screws.





vMax Trac Install Guide

4. Run the GPS4-CBL cable through the hole from the VML Controller and connect it to the card reader.



5. Thread the cable connector in the hole and reattach the card reader to the back plate.



6. Connect the other 2x2 microfit jack from the GPS4-CBL cable to the VML Controller's AUX1 socket. Continue wiring the VML, then power on and test.

